





1 year service 9 year service 9 year service

2001 - Epoxy E-303, MIL-P-24441 F150 & F151, Devcon. Most of the Devcon is gone in 9 years due to poor intercoat adhesion to the epoxy.



2000 - Epoxy E-303, MIL-P-24441 F150 & F151,Devcon Coat after 8 years service.



2001 - Vinyl VZ-108, V-106 after 24 years service.

White area is river scum. There is a minor amount of rust on the edge of each rib. All other areas are protected.